

## **Tool List**

## **Inside Electrician**

Each Journeyworker shall be required to furnish a standard conventional kit of tools necessary to perform their classification of work as follows:

- 1 Claw hammer
- 2 Phillips screwdrivers (large & small)
- 2 Screwdrivers
- 1 Keyhole saw
- 1 Plumb bob
- 2 Pair channel locks
- 1 Torpedo level
- 1 Diagonal pliers
- 1 Knife
- 1 8" Side cutters
- 1 Hacksaw frame
- 1 Needle nose pliers
- 2 Cold chisels (large & small)
- 1 Scratch awl
- 1 Set of Allen wrenches (up to and including 3/8" size)
- 1 Wood chisel
- 1 non-contact AC voltage sensor, Cat. IV rated to detect 50-1000 VAC
- 1 Crescent wrench 10" or 12"
- 1 Tap wrench (or combination 6/32", 8/32", 10/24" tapping tool)
- 1 6' rule or tape
- 1 Flashlight
- 1 Holding screwdriver
- 3 Combination wrenches, 7/16", 1/2", 9/16"
- 2 Nut drivers 3/8", 7/16"
- 1 Wire stripper
- 1 Center punch
- 1 Aviation snips
- Pencils
- 1 Tool box

The Employer shall furnish all wrenches of any description, 18" or more in length, hacksaw blades, cutting tools, bits, special tools of all kinds, and other necessary tools or equipment including facilities for delivering tools and materials to the job. Workers shall be held responsible for the tools or equipment issued to them providing the Employer furnishes the necessary lockers, tool boxes, or other safe places for storage.

June 1, 2020